



# MIT Research Reactor

Edward S. Lau

Assistant Director of Reactor Operations  
MIT Nuclear Reactor Laboratory

Big Impact of a Small Leak  
at the MIT Reactor

19 June 2023


# [ Leak Discovery ]

- December 12, 2022: 10% decrease in reading on one of the four nuclear safety channels
- All other neutron flux channels + thermal power channel indicate steady-state full power operation.
- Later that day: 4% decrease in a second nuclear safety channel
- The reactor was then shut down

# Water in Vertical Port Attenuated Signal (Fission Chamber removed in photo)



# Cross-Section of MITR



*Drawing courtesy of  
Dr. David Carpenter*

TRTR June 2023

# [ Identifying Source of Leak ]


- Lowering the core tank water level below the primary coolant outlet pipe stopped the leak.
- Raising the core tank water level above the primary coolant outlet pipe restarted the leak.

# Identifying Source of Leak

There were nine possible sources of primary water leakage at the level of the coolant outlet:


- Coolant outlet pipe/manifold
- Coolant inlet pipe/manifold
- Inlet differential pressure gages MP-6 and/or MP-6A
- Core tank overflow line/flange
- Core tank flange for core purge system piping
- Core tank level probes ML-3A and/or ML-3B
- Upper core tank gasket

# [ Cross-Section of MITR (Upper Tank) ]



# [ Core Tank (Interior)

- One pressure gage penetration visible
- One anti-siphon valve visible



# Shielding Removal After Defueling

- 1) Top shield lid (+ protective bag)
- 2) Upper shield access ring
- 3) Upper shield ring
- 4) Upper annular ring is not yet removed in this photo




# Upper Annular Ring (ok to stand on!)



# Leak is at Base of Upper Annular Ring



# View from Above (without Leak)




# [ Angled View from Above (with Leak) ]




# [ Close-Up View from Above (with Leak – 7.5 gallons per day)



[ All the Control Blade Drives and Wiring had to be Removed... ]




[ ...and then the Upper Annular Ring  
was Lifted Out using the Polar Crane ]



# Without the Upper Annular Ring...



[ ...there was Access to Replace  
the MP-6A (and MP-6) Pipes ]



# What Caused the Leak?

- Corrosion to a 1/2" threaded aluminum pipe section for the MP-6A flow sensor
- Humid conditions prolonged in the area
- Iron rust covered the aluminum pipe!
- The rust acted as an oxygen reduction site, polarizing the aluminum above its corrosion potential, resulting in general localized corrosion.



*Standard catalog part  
costing about \$5 !*

# Corrective Actions

- The leaking aluminum threaded pipe was replaced with a 316 stainless-steel threaded pipe.
- Other threaded piping in the area was similarly replaced as a preventive measure
- The piping area was cleared of iron rust.
- The inner and outer surfaces of the shield rings that sit above the piping area were carefully cleaned by grinding and sanding, and then coated with rust inhibitor.
- All gaskets in the area were inspected; some were replaced.
- Leak detectors added in many locations for early detection. Use of humidity sensors is being considered as well.
- Inspection tubes added for future use.

# Lessons Learned

- Excellent foresight in reactor design that allows disassembly and re-assembly.
- Notifying NRC via phone call to Project Manager early in the process and throughout the repair worked well.
- Notifying the MIT Reactor Safeguards Committee throughout the repair process worked well.
- Adhering to ALARA throughout the diagnostic and repair process worked well. – Defueling the core tank was a sound investment in terms of personnel dose exposure.
- Tap-holes should go deep enough for threaded pipe to have at least six threads of engagement. The MP-6/6A pipes went only about 2-1/2 threads deep, and attempted to compensate for this with a weld that was likely contaminated by pipe-dope.

# Questions & Answers



TRTR June 2023