

# Safety and reliability improvements in OSIRIS

C. BLOCQUEL

Nuclear Energy Direction Department of Reactors and Nuclear Services

CEA/SACLAY, 91191 Gif-sur-Yvette cedex, FRANCE




# **CEA Saclay – Main nuclear facilities**



DSM/Saclay – DANS - Department of Reactors and Nuclear Services TRTR – IGORR **12 meeting – Knoxville (USA) – September 19-24, 2010** 

#### THE EXPERIMENTAL PLATFORM







#### **MAIN EVENTS**


<ul> <li>Start of construction</li> </ul>	end of 1963
<ul> <li>Installation authorised</li> </ul>	08/06/1965
<ul> <li>First divergence ISIS</li> </ul>	28/04/1966
<ul> <li>First divergence OSIRIS</li> </ul>	08/09/1966
<ul> <li>First cycle OSIRIS</li> </ul>	08/09/1966
<ul> <li>Power 50 MW</li> </ul>	07/10/1966
<ul> <li>Power 70 MW</li> </ul>	11/12/1968
<ul> <li>New core Caramel</li> </ul>	25/07/1979
<ul> <li>Conversion to Silicide fuel OSIRIS</li> </ul>	1996
<ul> <li>Silicide core in ISIS</li> </ul>	Nov 1998
<ul> <li>Safety reassessment</li> </ul>	Nov 1999



 $\Delta$ 

#### **VERTICAL SIGHT**










Safety function : Reactivity 1992-93 Replacement of instrumentation and control -Centralized data processing finished in 93

1996-97 Replacement of fuel housing (and conversion Caramel to Silicide)

2005 Upgrading emergency panel2004-06 Replacement of instrumentation and control of


















2004

2006

2007

2009

#### **Safety function : Containment**

- **1988-89** Doing up of the liquid waste storage tanks
- 1994-95 Doing up of decay tanks on primary core and pool circuits
- **1999-2000** Doing up the 1, 2 & 3 channels

2000-03 Upgrading static confinement

**Decay tanks inspection** 

**Decay tanks inspection** 

Core decay tank casing repair

🚥 🗒 ac coeur C11

2001-02 Replacement of core tank **Double containment on liquid waste** storage tanks Liner on channel n°3








# **STATIC CONTAINMENT UPGRADING OPERATIONS**

œ



2001

2005-07

- 1977Isis pool refurbishment
  - Containment fissures repairs
  - Batches containment upgrading
    - Registers and valves on ventilation circuit
- 2003-06 Regulation ventilation valves

Extension of channel door Gaseous effluents room

2008Replacement of a containment

g

containment

ing and cleaning hot cell














9



**Safety function : Radioprotection** 

1983Radiation Protection Control Panel2000 & 2005 Refurbishment of survey devices<br/>of secondary circuit activity

- 2004-06 Replacement of information treatment units
- 2008 Setting of flow-meters inside ventilation exhaust chimney





œ



- **Support functions**
- 1988-1989 Complete revision of emergency power units
- 1990 Replacement of 48 V supply network
  - Replacement of low voltage switchboards
- 1999-2000 Requalification of emergency power units
- 2000 Replacement of rectifyers and wavers

2005-07 Heavy maintenance of diesel engines and alternators

2004-08 Replacement of HV/LV Transformers








DSM/Saclay – DANS - Department of Reactors and Nuclear Services TRTR – IGORR **12 meeting – Knoxville (USA) – September 19-24, 2010** 

#### SAFETY IMPROVEMENT 2008 - 2010








#### **Hoistering improvement**




Fiability improvement of lifting means (hot workshop crane – Osiris crane – Isis crane – other hoists)













Trolley anti-derailment

DSM/Saclay – DANS - Department of Reactors and Nuclear Services TRTR – IGORR **12 meeting – Knoxville (USA) – September 19-24, 2010** 





#### **Post-accident ventilation**






#### **Trucks' hatch**



In order to give an extension of the containment during loading and unloading phases





#### **Control rods mechanisms room's containment**



Upgrade the tightness of the room in order to reduce radioactive liquid transfers to the environment

# Heavy operation (5 months)






#### Limit the pool level's going down



In case of a leak towards control rods mechanisms room or a BORAX accident, limit the pool level's going down and avoid overflows in the plant







#### **Increase the tightness and strength of the structures**


Walling up PANES and SIDE-LIGHTS on Isis and hot workshop structures






#### Increase the tightness and strength of the structures







## Automatic shutdown in case of external hazards





#### **Forecast schedule**

